

PIN OUTS

M & C connector

Pin A Signal GND
Pin B Temp. Monitor
Pin C Power Monitor
Pin D Summary Alarm
Pin E HPA Mute Control

Pin F RS-485 -

Pin G RS-485 +

Pin H RS-232 Rx.....OPTIONAL

Pin J RS-232 Tx

Pin K RS-232 GND

Pin L LO Monitor

Pin M GND

Analogue M&C (Standard) uses a subset (A-E, L-M).

Digital M&C (optional) uses everything (adds RS-232/485).

AC Connector

A = Line

B = GND

C Neutral